No . 255 2005年9月

(YSK-N-88)

日本の港湾の舗装と荷役機械の実態調査結果について

田渕 郁男*

要旨

港湾の荷役の迅速化を求めるユーザーの希望は強く24時間荷役の開始,IT化による輸出入手続の迅速化が進められている。舗装に対する負荷の増加は顕著であるが、この分野に関しては、港湾技術研究所の時代から専門に研究する研究室が無く、海外の港湾の舗装の研究のフォローなどされていなかった。

そこで本研究では従来の日本の港湾の技術上の基準で作られ、供用されている岸壁等の舗装の破損 実態に関するアンケート調査(含む写真による実態撮影)と荷役機械の種類、吊り上げ能力等に関す る調査をメーカーへのヒアリング調査等により行ったものである.

これにより以下の知見を得た.

- (1) 日本の港湾の舗装で修繕が緊急に必要とされる施設が相当あり、5年から10年以内に修繕が必要とされる施設は5割に近い可能性がある.
- (2) 舗装の維持管理要領が全国で整備されておらず、点検方法、点検記録のデータベース化など未確立である.
- (3) 半たわみ性舗装、PC版、RC版などの使用が増加し、ブロック舗装は使われていない.
- (4) 荷役機械については、A G V 及びリーチスタッカなどが使われており、トランスファークレーン は 4.1 t が主流となっている .
- (5) トラッククレーンのアウトリガーの接地圧は、他の港湾荷役機械より格段に大きく、アウトリガーの下に剛性のある広い鉄板を敷くことが必要である.

これらの結果は新しい港湾の施設の技術上の基準の基礎資料となる.

キーワード:港湾の舗装、荷役機械、実態調査、維持管理

*沿岸海洋研究部沿岸海洋新技術研究官

〒239-0826 横須賀市長瀬3-1-1 国土交通省国土技術政策総合研究所

電話:046-844-5026 Fax:046-844-5081 e-mail:tabuchi-i92y2@nilim.go.jp

A Result of Investigation into the Actual Conditions of Japanese Ports Pavement and Cargo Handling Machines

Ikuo TABUCHI

Synopsis

There are many requests that speeding up of Cargo Handling Time in Ports from users . Then we have starting of 24 hours of cargo handling and requesting for speeding up export and import procedures by IT . So it's clear that increasing of load for port pavement . But there wasn't research division of ports pavement from PHRI and there wasn't a researcher had researched foreign countries studies for port pavement .

So I studied the actual conditions of Japanese ports pavement and cargo handling machines . The former was done by questionnaire survey (included photography of real pavement condition) . The latter was mainly done by hearing survey for cargo handling machines makers .

The results are

- 1) There weren't a few facilities which need emergency repair and it was possible half facilities would need to repair in 5-10 years .
- 2) There was not a manual of maintenance management for ports pavement in the whole country and inspection method and database code of inspection reports were not established.
- 3) Half flexile pavement, PC plates, RC plates were increased and there was not a block pavement .
- 4) For speeding up of cargo handling time, AGV and reach stack are used recently . Almost all transfer cranes are 41t hoisting .
- 5) Truck cranes have particularly bigger placed pressure than other handling machines . Then we need to seat large strict steel plates when we use a truck crane .

Key Words: pavement for ports, handling machine, investigation into the actual conditions, maintenance management

^{*}Coordinator for Advanced Coastal and Marine Technology, Coastal and Marine Department