

#### **参考4. 追跡調査における現場路面写真**

国道7号 秋田県由利本荘市

# H14 R7由利本荘（施工後1ヶ月）


1-1(1). わだち部



1-1(2). わだち部(接写)



1-2(1). 非わだち部




1-2(2). 非わだち部(接写)



H15 R7由利本荘（施工後16ヶ月）


1-1(1). わだち部



1-1(2). わだち部(接写)



1-2(1). 非わだち部



1-2(2). 非わだち部(接写)




H16 R7由利本荘（施工後24ヶ月）

1-1(1). わだち部




1-1(2). わだち部(接写)



1-2(1). 非わだち部




1-2(2). 非わだち部(接写)




H17 R7由利本荘（施工後35ヶ月）

1-1(1). わだち部




1-1(2). わだち部(接写)



1-2(1). 非わだち部



1-2(2). 非わだち部(接写)



H18 R7由利本荘（施工後47ヶ月）

1-1(1). わだち部



1-1(2). わだち部(接写)



1-2(1). 非わだち部



1-2(2). 非わだち部(接写)



H19 R7由利本荘（施工後59ヶ月）

1-1(1). わだち部



1-1(2). わだち部(接写)



1-2(1). 非わだち部



1-2(2). 非わだち部(接写)

